



## TEST REPORT

No. : TJAT1709010828NM

Date : Oct 23, 2017

Page: 1 of 5

CUSTOMER NAME: ONERPRO TECHNOLOGIES CORP.

ADDRESS: 5511, 11 Brunel Court, City Place, Toronto, Ontario M5V 3Y2

The following sample's information(s) was/ were submitted and identified on behalf of the client as:

**Sample Name** : ONERPRO Paint Protection Film  
**SGS Ref No.** : TJIN1709013452MR  
**Date of Receipt** : Sep 25, 2017  
**Testing Start Date** : Sep 26, 2017  
**Testing End Date** : Oct 20, 2017  
**Test Result(s)** : For further details, please refer to the following page(s)

Signed for and on behalf of  
SGS-CSTC Standards Technical  
Services(Tianjin) Co., Ltd

.....  
Lisa Jin  
Lab Supervisor



## TEST REPORT

No. : TJAT1709010828NM

Date : Oct 23, 2017

Page: 2 of 5

### Report Declaration:

The test samples were provided and confirmed by the customer in this report, the results contained in this test report do not relate to other samples of the same product. The manufacturer should ensure that all products manufactured are in conformity with the product sample in this report.

### Manufacture Declaration or Comment:

None

### Summary of Result(s):

No.	Test Item	Test Method	Conclusion
1.	Water Resistance (Immersion Method)	Provided by client	Pass

**Note:**  
Pass: Meet the requirements  
Fail: Does not meet the requirements  
N/A: Not apply to the judgment


## TEST REPORT

No. : TJAT1709010828NM

Date : Oct 23, 2017

Page: 3 of 5

Original Sample Photo:



## TEST REPORT

No. : TJAT1709010828NM

Date : Oct 23, 2017

Page: 4 of 5

1. Test Item: Water Resistance (Immersion Method)

Test Method: Provided by client

Test Condition:


Water temperature: 40°C

Duration of the test: 400h

Test Result:

Sample	Test Result	Requirement	Conclusion
1	Paint protection film has no detrimental effect. After ripped off the protect film, paint has no detrimental effect.	Paint protection film has no detrimental effect. After ripped off the protect film, paint has no detrimental effect.	Pass

Test Photo:




## TEST REPORT

No. : TJAT1709010828NM

Date : Oct 23, 2017

Page: 5 of 5



Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Water Bath chamber	38	POL-114	2016-11-07	2017-11-06

\*\*\*\*\* End of report\*\*\*\*\*